GEORGETOWN

Trrigation, Water and Wastewater Utility Cross Connection Section Test and Maintenance Report

40 miles and	-		
175	~	3-	
		B	THE REAL PROPERTY.

*New Installati	ion 🕱 Date	4 29 72 Wat	er Meter #	Peri	nit #			
**Annual Test	O Data	TY LANDS C	*Semi-Annual T	est O I	Date:			
Owner/Business	Name: HIGHL	AND HOME	S Phone Numb	per: 977 - 78	39-3500	ó E		
		Device Location:						
Manufacturer:	FEBCO	Reason dev	vice is installed: _	[PRIGATION	W/POTABLE	JAR		
RP DC_		SVB DCDA						
		ESSURE PRINCIPLE						
	DOUBLECHE First check	CK ASSEMBLY Second check	Relief valve	Air relief	Check valve			
INITIAL TEST	closed tight leaked p.s.i. 2	closed tight leaked	opened at	opened at	closed at			
		p.s.i. 7.5	p.s.i.d.	p.s.i.d.				
	RPZ	p.s.t		Did not open □	Did not close □			
BACKELOW STATUS (GIRGLE)	(PASS)	FAIL						
MATTERIALS	PASS	FAIL				USS		
AND REPAIRS								
TEST AFTER	closed tight p.s.i.	closed tight	opened at	opened at	closed at			
REPAIRS	RPZ p.s.i.d.	p.s.i	p.s.i.d.	p.s.i.d.	p.s.i.d.			
I certify the abo	ve information to be t	rue and correct to the l	pest of my knowled	ige.				
Property owner	er/occupant: High	HLAND HOL	AESOwner/Co	ntact: High	LAHD HOW	ies		
Certified Teste	r: (printed and signe	d) Lewis R.S	SINCLAIR					
Mailing address	ss: 1307 MAZ	HADO ROAL	City: CEL		Zip: 7861	3		
Tester Certif. n	umber: BPCO	U18 5	Gauge Seria	BAC LELE				
Tester's phone	number: 512-1	563-8162	Manufactu	reiliklikli TEDM	Iodel BAC FLO	.3		
ONLINE AT MYPER	RMITINOW.ORG FOR REOL	Please forward this of the DORIGINAL TEST FORM MITTED INSPECTION. NEW JOURNAL TOGETHER MITTED	<u>UST BE PLACED IN TH</u> INSTALLATIONS THAT	TARE PART OF NEW CO	ONSTRUCTION FROM THE	F		
INSPECTION. Qu **ANNUAL /SEM.	estions, please call our offi <u>I-ANNUAL TEST:</u> City of G	ce at (512) 930-2550 – <u>Billi</u> Georgetown Customer Care C	na questions, please of	all Customer Service at 5	12)930-3 64 0.			
E-mail: customercal	**TEST	hin 10 business days of it RECORDS MUST BE KEPI	FOR AT LEAST THR	EE YEARS**	vater service.			
USE ONLY MANUFACTURER'S REPLACEMENT PARTS								