City of Georgetown - Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly tested for recordkeeping *purposes:

City of Georgetown 2460001 PO Box 1430 **Contact Name: Customer Care** Georgetown, Texas 78626 Phone Number: 512-930-3640

BPAT Information

Company Name: Safewater Backflow and Irrigation

Brad Weyant Tester Name: Address: 609 E 50TH

AUSTIN, Texas 78751

Phone Number: 5126059790

Email Address: brad@safewateratx.com

License Number: BP0016935 License Expiration: 12/3/2024

Contact Information

Property Type: Residential **Company Name: Business Name:**

Property Address: 205 Lockhart Dr

Liberty Hill, TX 78628

Contact Name:

Mailing Address: 205 Lockhart Dr Liberty Hil, TX 78628

10/7/2021

Phone Number:

Email Address:

The backflow prevention assembly detailed below has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters.

Backflow Method: Double Check Valve

Main Assembly Manufacturer: Febco Model: 850 Size: 1 Serial Number: HF59073

Location: Left front yard 5 feet from meter Hazard Type ****: Irrigation - Non Chemical

Test Result: Passed New Installation Reason for Test:

Is the assembly installed in accordance with manufacturers recommendations and/or local codes? Yes

Is the assembly installed on a non-potable water supply (auxiliary)? No

Differential pressure Midwest 845-5 (potable) Serial Number: 10150482 **Date Tested for Accuracy:**

gauge used:

	Double Check Valve	
	Check Valve #1	Check Valve #2
Initial Test	Held at 1.2 PSID	Held at 1.2 PSID
Date: 3/17/2022	✓ ClosedTight	✓ ClosedTight
Time: 2:40 PM	Leaked	Leaked
Repairs and Materials Used		
Repair Details		
Test After Repairs	Held at 0 PSID	Held at 0 PSID
	Closed Tight	Closed Tight

Remarks

^{*} TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS [30 TAC 290.46(B)]

^{**} USE ONLY MANUFACTURER'S REPLACEMENT PARTS

^{*** 2}nd Check: Numeric reading required for double check valve only.