

Service Address

Hazard/CCID: 42215

Backflow Prevention Assembly Test Report

SAN MARCOS, TX 78666

Location: 241 Blue Oak Blvd

Meter#:

LID/Service:

Account #:

Serial #: HF 96437 Check if Correct Corrections

Manufacturer: Febo

Model: 850

Type: DC

Size: 1"

Orientation: At meter

Protection: Immigation

Site Use:

Hazard:

Mailing Address

241 Blue Oak Blvd
San Marcos, TX 78666

Test Due No Later than:

Existing Removed
New Replaced

Commercial Industrial Residential Municipal

Domestic Irrigation Fire

Reduced Pressure Principle Assembly

Double Check Valve Assembly

PVB/SVB

Check Valve #1

Check Valve #2

Relief Valve

Air Inlet

Check Valve

Initial Test

Leaked

Leaked

Did not open

Leaked

Date 4/6/22

Closed Tight

Closed Tight

Did not open

Opened Fully Yes

No

Time 4:55 pm

Pass Fail

Held at 1.8 PSID

Held at 1.4 PSID

Opened at ___ PSID

Opened at ___ PSID

Held at ___ PSID

Repairs

Cleaned

Rubber Kit

Rebuild

Replaced

Other

Date _____

Time _____

Final Test

Closed Tight

Closed Tight

Opened Fully

Date _____

Time _____

Pass Fail

Held at ___ PSID

Held at ___ PSID

Opened at ___ PSID

Opened at ___ PSID

Held at ___ PSID

Air Gap

Date _____

Time _____

Diameter _____

Separation _____

Pass Fail

Comments:

Proper Installation Yes No

RV Exercised Yes No

#2 Shutoff Closed Yes No

Service Restored Yes No

I certify all information on this report is true & accurate, acknowledging that incomplete reports will not be accepted.

Tester Scott Stevenson Signature [Signature]

Certification # BP0017507 Expire 12/21/22 Phone 512-294-3826

Test Kit Serial # 06163433 Calibration Date 10/11/21

Company bt Fire Safety Phone 512-777-1555

Line Pressure 60 psi

Meter Reading _____

Test Results

Pass Fail



Submit completed
Test Report:

630 E HOPKINS ST

SAN MARCOS TX 78666

512-393-8008 Fax:

SODONNELL@SANMARCOSTX.GOV