Irrigation, Water and Wastewater Utility Cross Connection Section Test and Maintenance Report

*New Installation	on 🕱 Date:	5372 Wat	r Meter # Permit #			
**Annual Test O Date: **Semi-Annual Test O Date: Commercial O Commercial O						
					•	
Owner/Business	Name: DREE	5 HOMES	Phone Numb	er: 214-14-1	- 1100	
Model Number:	250 Size: _1	Device Location:	4 5% 0	METERSerial N	umber: HG 00	24
Manufacturer: FEBCO Reason device is installed: IRIGATION / POTABLE WATER						
RP DC_		VB DCDA			A .*	
	REDUCED PR	ESSURE PRINCIPLE	ASSEMBLY	PRESSUREWA	CUUMBREAKER S	
	DOUBLECHECK ASSEMBLY		Relief valve	Air relief	Check valve	
	First check	Second check				
INITIAL TEST	closed tight leaked	closed tight leaked	opened at	opened at	closed at	
	p.s.i. <u> </u>	p.s.i. 2.4	p.s.i.d.	p.s.i.d.	p.s.i.d.	
	RPZp.s.i.d.			Did not open 🗆	Did not close □	
BACKELOW STATUS (GIRGLE)	PASS	FAIL				
MATERIALS AND REPAIRS						
TEST AFTER	closed tight	closed tight	opened at	opened at	closed at	
REPAIRS	.p.s.i RPZ	p.s.i		p.s.i.d.	p.s.i.d.	
	p.s.i.d.		p.s.i.d.	p.s.i.u.	p.s.i.u.	
I certify the above information to be true and correct to the best of my knowledge.						
Property owner/occupant: DREES HOMES Owner/Contact: DREES HOMES						
Certified Tester: (printed and signed) LEVIS R. SINGUAIR						
Mailing addres	s: 1307 MAZ	HADO ROAL			TYZip: 7861	3
Tester Certif. n	umber: BPCO	U815	Gauge Seria	al: 03/62	474	e
Tester's phone	number: 51'2-5	43-8162	Manufactu	reiLiNLINITEDIV	IodelBAC-FLO	3
ONLINE AT MYPER. GROUND UP, ORIGINSPECTION. Que **ANNUAL /SEMI E-mail: gustomercan	MITNOW.ORG FOR REQU MINAL REPORT MUST BE estions, please call our office -ANNUAL TEST: City of G e@georgetown.org	Please forward this of D ORIGINAL TEST FORM MIRED INSPECTION. NEW 1 SUBMITTED TOGETHER W. Le at (512) 930-2550 – Billio deorgetown Customer Care Control of the 10 business days of in	UST BE PLACED IN THE INSTALLATIONS THAT INSTALLATIONS THAT INTH JOB PACKET AND ING Questions, please carefully aspection may result inspection may result inspection may result in the Installation in the Ins	TARE PART OF NEW CO IN INSPECTED DURING IN Customer Service at 5: I Ave, P O Box 1430, Geo It in disconnection of u	ONSTRUCTION FROM THE NG THE BUILDING FINAL 12)930-3640. progetown, Texas 78627.	⊑
Failure to return this form within 10 business days of inspection may result in disconnection of water service. **TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS** ***HEE ONLY MANUFACTURER'S REPLACEMENT PARTS***						