

City of Pflugerville - PWSID #2270014



Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly tested. A signed and dated original must be submitted to the public water supplier for record keeping *purposes

Customer Information		PWS Information	
Customer / Property Name:	Resident	PWS Contact Name:	David Denby
Contact Name:		PWS Phone Number:	(512) 990-6427
Property Address:	6524 Covina Ln Pflugerville, TX 78660	PWS Address:	15500 Sun Light Near Way #B Pflugerville, TX, 78691

The backflow prevention assembly detailed below has been tested as required by TCEQ regulations and is certified to be operating within acceptable parameters.

Assembly Information

Type:	DC	Model #:	850
Size:	1"	Serial#:	HF58823
Manufacturer:	Febco	BPA Serves:	Irrigation
Location:	left front yard 5 ft from meter		

Reason for test: new existing replaced.
 Is the assembly installed in accordance with manufacturer recommendations and/or local codes? yes no
 Water supply: Potable

PASS

Test Date: 2022-04-05

Assembly Test Information

Initial Test (Time: 06:00 pm)	
Check Valve #1 : 1.9 (X) Closed Tight/Held () Leaked	Check Valve #2 : 1.9 (X) Closed Tight/Held () Leaked
Final Test (Time: 06:00 pm)	
Check Valve #1 : 1.9 (X) Closed Tight/Held () Leaked	Check Valve #2 : 1.9 (X) Closed Tight/Held () Leaked

As the tester of record, I affirm this test as: Passed Failed **Repairs Made:** No**

Additional comments or repairs made / materials (parts) used:
(no comments)

Tester Information

Tester Name:	Weyant, Brad	Custom Questions
Tester License Expiration:	12-03-2024	Is the assembly installed in accordance with manufacturer recommendations and / or local codes? Y/N
Certification#:	BP0016935	
Test Kit Serial #:	10150482	y
Test Kit Date Tested for Accuracy:	10-07-2021	Bypass identifying information (manufacturer, model, serial number, and size)
Test Kit Mfr. & Mod. #:	Mid-West 845-5 (Potable)	
Testing Co Name:	Safewater Backflow and Irrigation	
Phone:	(512) 605-9790	
Address:	PO Box 4002 Austin, TX 78765	

The above tester certifies that all information submitted for this report is true and accurate
* TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS [30 TAC §290.46(B)]
** USE ONLY MANUFACTURER'S REPLACEMENT PARTS

The backflow prevention assembly detailed above has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters