

Backflow Prevention Assembly Test Details



**Test and Maintenance Report**

Water System ID# 2270001

Special Services Division  
3907 South Industrial DR  
Austin, TX 78744-1070

Phone: (512) 972-1060  
FAX: (512) 972-1260



\*\*\* Test records must be kept by the customer for at least three years \*\*\*

**Backflow Assembly Information**

<b>Serial Number:</b>	HF83177	<b>Manufacturer:</b>	FEBCO
<b>Model:</b>	850	<b>Size:</b>	1
<b>Service Address:</b>	9604 BAYSHORE BND 78726		
<b>Assembly location on the property:</b>	10' NORTHWEST OF METER.		
<b>Reason the assembly is installed:</b>	IRRIGATION W/ CITY POTABLE WATER		
<b>Is this assembly installed to code requirements?</b>	Yes		

**Customer Information**

<b>Property Owner / Agent:</b>	TAYLOR MORRISON
<b>Mailing Address:</b>	1
<b>City / State / Zip:</b>	AUSTIN, TX 78717
<b>Phone:</b>	(512) 243-8275

**Backflow Test**

Initial Test	DCVA	
	Check Valve #1	Check Valve #2
	2.3 PSID	2.3 PSID

**Repairs**

**Test After Repairs**

<b>Test Date:</b>	Apr 5, 2022
<b>Backflow Test Status:</b>	Passed

**Tester Information**

The backflow technician listed below has previously certified that the information on this report was true and correct on the date of this test.

<b>Backflow Technician:</b>	SINCLAIR, LEWIS R
<b>License:</b>	BP0002815
<b>Gauge Serial Number:</b>	03162474