

Backflow Prevention Assembly Test Details



Test and Maintenance Report

Water System ID# 2270001

Special Services Division
3907 South Industrial DR
Austin, TX 78744-1070

Phone: (512) 972-1060
FAX: (512) 972-1260



*** Test records must be kept by the customer for at least three years ***

Backflow Assembly Information

Serial Number:	HG02413	Manufacturer:	FEBCO
Model:	850	Size:	1
Service Address:	1120 DENFIELD ST BLDG 1 78721		
Assembly location on the property:	CENTER FRONT YARD NEAR METER		
Reason the assembly is installed:	IRRIGATION W/ CITY POTABLE WATER		
Is this assembly installed to code requirements?	Yes		

Customer Information

Property Owner / Agent:	DENFIELD HOMES
Mailing Address:	
City / State / Zip:	
Phone:	

Backflow Test

Initial Test	DCVA	
	Check Valve #1	Check Valve #2
	2.2 PSID	2.4 PSID
Repairs		
Test After Repairs		
Test Date:	May 18, 2022	
Backflow Test Status:	Passed	

Tester Information

The backflow technician listed below has previously certified that the information on this report was true and correct on the date of this test.

Backflow Technician:	WEYANT, BRADLEY
License:	BP0016935
Gauge Serial Number:	10150482