

BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

The following form must be completed for each assembly tested. *DO NOT LEAVE THIS REPORT IN METER BOX* A signed and dated **ORIGINAL** must be submitted to the public water supplier.

ILLEGAL	OR INCOMPLET	E REPORTS WILL	NOT BE ACCEPTED
---------	--------------	----------------	------------------------

RESIDENTIAL COMMERCIAL Is the assembly installed in accordance with manufacturer recommendations and/or local codes?								
BACKFLOW ASSEMBLY INFORMATION Serial Number HF99648 Manufacturer Febco	850							
Occupant/Business Name Empire								
Physical Address 20502-A Tractor Dr.								
Assembly Location on Property Front yard 5 feet from meter								
Purpose of Assembly Irrigation								
CUSTOMER INFORMATION Property Owner/Agent_Empire								
2050Z-A Tractor Dr. Mailing Address	_Bldg	_Suite#						
City PflugervilleTX	Zip Code 7866	60						

The backflow prevention assembly detailed below has been tested and maintained as required by TCEQ regulations and is certified to be operating within acceptable parameters.

Reduced Pressure Principle

Pressure Vacuum Breaker

Double Check Valve

TYPE OF ASSEMBLY

Reduced Pressure Principle Detector Double Check Detector Spill-Resistant Pressure Vacuum Breaker

	REDUCED PRESSURE BACKFLOW PREVENTION ASSEMBLY			PRESSURE VACUUM BREAKER		
	DOUBLE-CHECK VALVE ASSEMBLY					
	1 ST CHECK	2 ND CHECK	RELIEF VALVE	AIR INLET	CHECK VALVE	
INITIAL TEST	Held at 2.2 psid	Held at 2.2 psid	Opened at psid	Opened at psid	Held atpsid	
	Closed Tight Leaked	Closed Tight Leaked	Did not open	Did not open	Leaked	
TEST AFTER REPAIRS	Held atpsid	Held at psid	Opened at psid	Opened at psid	Held atpsid	
	Closed Tight	Closed Tight				
REPAIRS AND MATERIALS USED						
Test gauge used: Make/Model: Mid West 845			_{SN:} 1015048	32 Calibration I	Date: 10/7/2021	

*TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS. **USE ONLY MANUFACTURER'S REPLACEMENT PARTS.