## Irrigation, Water and Wastewater Utility Cross Connection Section Test and Maintenance Report

_1	OOP	
-		

*New Installation Date: 8 10 22 Water Meter # Permit #							
**Annual Test O Date: **Semi-Annual Test O Date:							
Address: 137	SHADYS	spring tr		Comme	rcial O		
Owner/Business Name: HIGHLAND HOMES Phone Number:							
Model Number: Size: 1 Device Location: 4'SSW F METERSerial Number: HG19890							
Manufacturer: FEBCO Reason device is installed: IRRIGATION FOTABLE VIATE							
RPDC		VB DCDA					
	REDUCED PR	ESSURE PRINCIPLE	ASSEMBLY	PRESSURE VA	GUUN BREAKER		
	DOUBLECHE First check	CK ASSEMBLY Second check	Relief valve	Air relief	Check valve		
INITIAL TEST	closed tight leaked p.s.i. 2.5	closed tight leaked	opened at	opened at	closed at		
		p.s.i. 2.7	p.s.i.d.	p.s.i.d.	p.s.i.d.		
	RPZ			Did not open 🛚	Did not close □		
BACKELOW STATUS (CIRGLE)	(PASS)	FAIL					
MATERIALS AND REPAIRS			ì		II.		
	closed tight	closed tight	opened at	opened at	closed at		
TEST AFTER REPAIRS	p.s.i RPZ p.s.i.d.	p.s.i	p.s.i.d.	p.s.i.d.	p.s.i.d.		
I certify the above information to be true and correct to the best of my knowledge.							
Property owner/occupant: Highiand Homes Owner/Contact:							
Certified Tester: (printed and signed) LEWIS R. SINGLAIR Deiro R. A. A. R. C.							
Mailing address: 1307 MACIADO ROAD City: CEDAR PAZState: TX Zip: 78613							
Tester Certif. number: Process Gauge Serial: 03 62474							
Tester's phone number: 517-563-8162 Manufactureninii/11720ModelBAC-FLO-3							
ONLINE AT MYPERM GROUND UP, ORIGI INSPECTION. Ques **ANNUAL /SEMI E-mail: customercare	ATTNOW.ORG FOR REQUIRED FOR REQUIRED FOR REPORT MUST BE STITUTED FOR ANNUAL TEST: City of Google organization with the return this form with the return the return this form with the return the r	Please forward this of D ORIGINAL TEST FORM MIRED INSPECTION. NEW 1 SUBMITTED TOGETHER W. at (512) 930-2550 — Billipeorgetown Customer Care Control of the C	UST BE PLACED IN THE INSTALLATIONS THAT INSTALLATIONS THAT INTH JOB PACKET AND Questions, please calenter, 300-1 Industrial Inspection may result	ARE PART OF NEW CO ID IS INSPECTED DURIN all Customer Service at 51 I Ave, P O Box 1430, Geo It in disconnection of w	ONSTRUCTION FROM THE NG THE BUILDING FINAL 12)930-3640. rgetown, Texas 78627.		

\*\*\*USE ONLY MANUFACTURER'S REPLACEMENT PARTS\*\*\*