

4050 FM 1660 Hutto, Texas 78634 512-759-1286 Fax 512-759-2983

BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

PWS I.D: 2460022

MAILING ADDRESS ____ 305 Flowers Ave. Hutto, TX 78634____ CONTACT PERSON _____Taylor Morrison____

LOCATION OF SERVICE 305 Flowers Ave. Hutto, TX 78634_____

INSPECTION DATE _12/1/2023_2:45PM_____

The backflow prevention assembly detailed below has been tested and maintained as required by TCEQ regulations and is certified to be operating within acceptable parameters.

TYPE OF ASSEMBLY

- () Reduced Pressure ZONE
- (X) Double Check Valve
- Pressure Vacuum Breaker ()

- () Reduced Pressure Principle-Detector
- () Double Check-Detector
- Spill-Resistant Pressure Vacuum Breaker ()

Manufacturer: Apollo____

Model # DC4A Serial # 54827C

Location of device Left front yard 5 feet from meter

Is the assembly installed in accordance with manufacturer recommendations and/or local codes? Yes_____

	Reduced Pressure Principle Assembly			Pressure Vacuum Breaker	
	Double Check Valve Assembly		Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check		Opened at psid	Held at psid
Initial Test	Held at 1.8 Psi	Held at 1.6 psid	Opened at psid	Did not Open 🛛	Leaked 🛛
	Closed Tight X Leaked □	Closed Tight X Leaked □	Did not open 🛛		
Repairs and Materials Used					
Test After	Held at psi Closed Tight □	d Held at psid Closed Tight □	Opened at psid	Opened at psid	Held At psid
Repair					

The above is certified to be true at the time of testing,

Test gauge used: Make / Model Mid West 845	SN: 10150482	Calibration Date:10/4/2023
--	--------------	----------------------------

Firm Name Safewater Backflow

Certified Tester: Brad Weyant

Firm Address PO Box 4002 Austin, TX 78765

Cert. Tester No: BP0016935

Firm Phone # 512-605-9790

Pressure 60PSI

- TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS ** USE ONLY MANUFACTURER'S REPLACEMENT PARTS