

4050 FM 1660 Hutto, Texas 78634 2983 512-759-1286 Fax 512-759-

BAC PWS I.D: 2460022	KFLOW PREV	ENTI	ON ASS	EMBLY	TEST AND M	MAINTE	NANCE REP	ORT		
MAILING ADDRESS	309 Doodle Ln. H	Hutto, T	X 78634							
CONTACT PERSONTaylor Morrison										
LOCATION OF SER										
INSPECTION DATE								_		
The backflow prever is certified to be ope	-				ed and maintai	ined as re	quired by TCE	Q regul	ations and	
				TYPE OF	ASSEMBLY					
() Reduced Pressure ZONE () Reduced Pressure Principle-Detector										
(X) Double Check Valve () Double Check-Detector										
() Press	sure Vacuum Brea	ker			() Spill-Re	esistant F	ressure Vacuu	ım Brea	ker	
Manufactu	rer: Apollo									
Model # Do	C4A		Ser	ial # 5478	2C					
Location of	device Right fron	t yard	5 feet fro	m meter _						
Is the assembly insta	alled in accordance	e with	manufact	urer recom	nmendations ar	nd/or loca	l codes? Yes_			
	Red	luced l	Pressure	Principle A	ssembly	Pressure Vacuum Breaker				
	Double Check	2nd Check		Relief Valve		Air Inlet		Check \	Check Valve	
	1st Check					Opened at	psid	Held at	psid	
Initial Test	Held at 1.9 Psi		Held at	1.8 psid	Opened at	psid	Did not Open		Leaked	
	Closed Tight Leaked	X	Closed Leaked	Tight X	Did not open					
Repairs and Materials Used										
Test After	Held at Closed Tight	psid	Held at Closed		Opened at	psid	Opened at	psid	Held At	psid
Repair										
The above is certif	fied to be true at th	ne time	e of testin	ıg,						
Test gauge used:	Make / Model Mid	l West	845	SN: 10	150482	Calibr	ation Date:10/	4/2023		
Firm Name Safewater Backflow					Certified Tester: Brad Weyant					
Firm Address PO Box 4002 Austin, TX 78765					Cert. Tester No: BP0016935					
Firm Phone # 512-605-9790 Pressure 60PSI										

- TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS ** USE ONLY MANUFACTURER'S REPLACEMENT PARTS