

4050 FM 1660 Hutto, Texas 78634

512-759-1286 Fax 512-759-

298

BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT PWS I.D: 2460022 MAILING ADDRESS_201 Oconee St. Hutto, TX 78634									
CONTACT PERSONTaylor Morrison									
LOCATIO	OCATION OF SERVICE 201 Oconee St. Hutto, TX 78634								
INSPECTION DATE _2/15/2024_10:30AM									
		e operating within acceptable pa		d maintained as required by TCEQ regulations and					
	( X)	Reduced Pressure ZONE	()	Reduced Pressure Principle-Detector					
	` '	Double Check Valve	( )	Double Check-Detector					
	()	Pressure Vacuum Breaker	()						
	Manuf	acturer: Apollo	_						
	Model # DC4A Serial # 63955C								
	Location of device Right front yard 5 feet from meter								

Is the assembly installed in accordance with manufacturer recommendations and/or local codes? Yes\_\_\_\_\_

	Reduced Pressure Principle Assembly			Pressure Vacuum Breaker	
	Double Check Valv		Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check		Opened at psid	Held at psid
Initial Test	Held at 1.7 Psi	Held at psid 1.6	Opened at psid	Did not Open	Leaked
	Closed Tight X Leaked □	Closed Tight X Leaked	Did not open □		
Repairs and Materials Used					
Test After	Held at psid Closed Tight	Held at psid Closed Tight □	Opened at psid	Opened at psid	Held At psid
Repair					

The above is certified to be true at the time of testing,

Test gauge used: Make / Model Mid West 845 SN: 10150482 Calibration Date:10/4/2023

Firm Name Safewater Backflow Certified Tester: Brad Weyant

Firm Address PO Box 4002 Austin, TX 78765 Cert. Tester No: BP0016935

Firm Phone # 512-605-9790

- TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS \*\* USE ONLY MANUFACTURER'S REPLACEMENT PARTS