City of Georgetown - Backflow Prevention Assembly Test and Maintenance Report The following form must be completed for each assembly tested for recordkeeping *purposes: 2460001 City of Georgetown PWS ID: Water Regulatory PO Box 1430 **Contact Name:** 512-930-3640 Phone Number: Georgetown, Texas 78626 **BPAT Information** 512-563-8762 **Phone Number:** Company Name: L Sinclair Services, Inc. lss@austin.rr.com **Email Address: Tester Name:** Lewis Sinclair License Number: BP0002815 Address: 1307 Machado Road 2/12/2026 Cedar Park, Texas 78613 License Expiration: Residential Company Name: **Property Type:** Contact Name: **Business Name:** 105 Old Woods Rd Property Address: 105 Old Woods Rd **Mailing Address:** Liberty Hill, TX 78642 Liberty Hill, TX 78642 **Phone Number: Email Address: Backflow Information** The backflow prevention assembly detailed below has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters. **Backflow Method:** Double Check Valve Model: DC4A Size: 1 Serial Number: 53420C Main Assembly Manufacturer: Apollo Location: 8' NW of meter Hazard Type ****: Irrigation - Non Chemical **Test Result:** Passed **New Installation** Reason for Test: Is the assembly installed in accordance with manufacturers recommendations and/or local codes? Yes Is the assembly installed on a non-potable water supply (auxiliary)? No Date Tested for Accuracy: 3/16/2023 Serial Number: 03162474 Differential pressure Bac-Flo Bac-Flo 3 (potable) gauge used:

	Double Check Valve	
	Check Valve #1	Check Valve #2
Initial Test Date: 10/11/2023 Fime: 12:30 PM	Held at 2 PSID ✓ ClosedTight Leaked	Held at 2 PSID ☑ ClosedTight ☐ Leaked
Repairs and Materials Used		
Repair Details		
Test After Repairs	Held at 0 PSID	Held at 0 PSID Closed Tight

Remarks