## **Backflow Prevention Assembly Test Details**



## **Test and Maintenance Report**

Water System ID# 2270001

Phone: (512) 972-1060 FAX: (512) 972-1260



Special Services Division 3907 South Industrial DR Austin, TX 78744-1070

\*\*\* Test records must be kept by the customer for at least three years \*\*\*

	D1 /	law Accombly Information		
		low Assembly Information		
Serial Number:	85277C	Manufacturer:	APOLLO/CONBRACO	
Model:	DC4A	Size:	1	
Service Address:		12402 DAIRYWORK RD 786	10	
Assembly location on the property:		4' FROM METER - FRONT LEFT		
Reason the assembly is installed:		IRRIGATION W/ CITY POTABLE WATER		
Is this assembly installed to code re	quirements?	Yes		
		Customer Information		
Property Owner / Agent:	Owner / Agent:		HOME OWNER	
Mailing Address:		12402 DAIRYWORK ROAD		
City / State / Zip:	BUDA, TX 78620			
Phone:				
		Backflow Test		
		DCVA		
Initial Test		Check Valve #1	Check Valve #2	
		2.4 PSID	2.2 PSID	
Repairs				
Test After Repairs				
Test Date:		Jun 18, 2024		
Backflow Test Status:		Passed		
		Tester Information		
The backflow technician listed belo	ow has previously certifie	ed that the information on this report wa	s true and correct on the date of this test	
Backflow Technician:		STEVENSON, SCOTT		
License:		BP0017507		
		06163433		