## City of Georgetown - Backflow Prevention Assembly Test and Maintenance Report The following form must be completed for each assembly tested for recordkeeping \*purposes:

City of Georgetown PO Box 1430 Georgetown, Texas 78626

PWS ID: **Contact Name:**  2460001

Phone Number:

Water Regulatory 512-930-3640

**BPAT Information** 

Company Name: **Tester Name:** 

**Property Type:** 

**Business Name:** 

Property Address:

Address:

L Sinclair Services, Inc. Lewis Sinclair

**Phone Number: Email Address:** 

512-563-8762

1307 Machado Road Cedar Park, Texas 78613 License Number: License Expiration: lss@austin.rr.com BP0002815 2/12/2026

Residential

**Company Name:** 

**Contact Name: Mailing Address:** 

516 Tradewinds Way Georgetown, TX 78628

516 Tradewinds Way Georgetown, TX 78628

**Phone Number: Email Address:** 

## Backflow Information

The backflow prevention assembly detailed below has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters.

**Backflow Method:** 

Double Check Valve

Main Assembly Manufacturer: Apollo Model: DC4A

Size: 1

Serial Number: 53311C

Location:

7' E of meter

Hazard Type \*\*\*\*:

Irrigation - Non Chemical

**Test Result:** 

Passed

Reason for Test:

New Installation

Is the assembly installed in accordance with manufacturers recommendations and/or local codes? Yes

Is the assembly installed on a non-potable water supply (auxiliary)? No

Differential pressure

Bac-Flo Bac-Flo 3 (potable)

Serial Number: 03162474

Date Tested for Accuracy:

3/16/2023

gauge used:

	Double Check Valve	
	Check Valve #1	Check Valve #2
Initial Test Date: 10/9/2023 Time: 1:45 PM	Held at 2.2 PSID  ☑ ClosedTight ☐ Leaked	Held at 2.3 PSID  ☑ ClosedTight ☐ Leaked
Repairs and Materials Used		11 18 - 1
Repair Details		
Test After Repairs	Held at 0 PSID  Closed Tight	Held at 0 PSID

Supply line pressure 75 psi