

## **Test and Maintenance Report**

Water System ID# 2270001

Phone: (512) 972-1060 FAX: (512) 972-1260



Special Services Division 3907 South Industrial DR Austin, TX 78744-1070

\*\*\* Test records must be kept by the customer for at least three years \*\*\*

	Backfid	ow Assembly Information		
Serial Number:	HF41344	Manufacturer:	FEBCO	
Model:	850	Size:	1	
Service Address:		5412 JASON DR 78723		
Assembly location on the property:		7' WEST OF METER.		
Reason the assembly is installed:		IRRIGATION W/ CITY POTABLE WATER		
Is this assembly installed to code requirements?		Yes		
	Cı	ustomer Information		
Property Owner / Agent:		TAYLOR MORRISON HOMES	TAYLOR MORRISON HOMES	
Mailing Address:		11200 LAKELINE BLVD #150A		
City / State / Zip:		AUSTIN, TX 78717		
Phone:		(512) 328-8866		
7.5.1.1.0.0.0.0.0.0.0.0.0.0.0.0.0.0.0.0.0		Backflow Test		
		DCVA		
Initial Test	Ch	neck Valve #1	Check Valve #2	
		2.7 PSID	0 PSID	
Repairs				
Test After Repairs	· · · · · · · · · · · · · · · · · · ·	2.2 PSID	2.5 PSID	
Test Date:		Nov 18, 2020		
Backflow Test Status:		Passed		
		Tester Information		
The backflow technician listed	d below has previously certified	that the information on this report was	true and correct on the date of this test.	
Backflow Technician:		SINCLAIR, LEWIS R		
License:		BP0002815		
Gauge Serial Number:		06111314		