

4050 FM 1660 Hutto, Texas 78634 2983 512-759-1286 Fax 512-759-

BAC PWS I.D: <b>2460022</b>	KFLOW PREVENT	TON ASSEMBLY	TEST AND M	IAINTEN	IANCE REP	ORT			
MAILING ADDRESS	311 Oconee St Hutte	o, TX 78634							
	lTaylor Morrison								
LOCATION OF SER	VICE 311 Oconee St	Hutto, TX 78634							
INSPECTION DATE	_10/13/2023_2:00PM_								
	tion assembly detailed		ed and maintaiı	ned as re	quired by TCE	Q regula	ations and		
		TYPE OF	ASSEMBLY						
() Reduced Pressure ZONE () Reduced Pressure Principle-Detector									
(X) Double Check Valve () Double Check-Detector									
() Press	ure Vacuum Breaker		() Spill-Re	sistant P	ressure Vacuu	ım Breal	ker		
Manufactur	er: Apollo								
Model # DC	C4A	Serial # 5317	1C						
Location of	device Right front yar	d 5 feet from meter _							
Is the assembly insta	lled in accordance wit			id/or loca					
	Reduced Pressure Principle Assembly				Pressure Vacuum Breaker				
	Double Check Valve Assembly		Relief Valve		Air Inlet		Check \	Check Valve	
	1st Check	2nd Check			Opened at	psid	Held at	psid	
Initial Test	Held at 1.8 Psi	Held at 1.6 psid	Opened at	psid	Did not Open		Leaked		
	Closed Tight X Leaked	Closed Tight X Leaked □	Did not open						
Repairs and Materials Used									
Test After	Held at ps Closed Tight □	d Held at psid Closed Tight □	Opened at	psid	Opened at	psid	Held At	psid	
Repair									
The above is certif	ed to be true at the tir	ne of testing,							
Test gauge used: N	Make / Model Mid We	st 845 SN: 10	150482	Calibra	ation Date:10/4	1/2023			
Firm Name Safewater Backflow			Certified Tester: Brad Weyant						
Firm Address PO	Box 4002 Austin, TX	78765	Cert. Te	ster No:	BP0016935				
Firm Phone # 512-605-9790 Pressure 60PSI									

- TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS \*\* USE ONLY MANUFACTURER'S REPLACEMENT PARTS