

Backflow Prevention Assembly Test Details



Test and Maintenance Report

Water System ID# 2270001

Special Services Division
3907 South Industrial DR
Austin, TX 78744-1070

Phone: (512) 972-1060
FAX: (512) 972-1260



*** Test records must be kept by the customer for at least three years ***

Backflow Assembly Information

| | | | |
|---|-----------------------------------|----------------------|-----------------|
| Serial Number: | 64540C | Manufacturer: | APOLLO/CONBRACO |
| Model: | DC4A | Size: | 1 inch |
| Service Address: | 12316 DAIRYWORK RD 78610 | | |
| Assembly location on the property: | LEFT FRONT YARD 5 FEET FROM METER | | |
| Reason the assembly is installed: | IRRIGATION W/ CITY POTABLE WATER | | |
| Is this assembly installed to code requirements? | Yes | | |

Customer Information

| | |
|--------------------------------|--|
| Property Owner / Agent: | TAYLOR MORRISON OF TEXAS INC |
| Mailing Address: | ATTN: ACCOUNTS PAYABLE RC0220 PO BOX 5136 |
| City / State / Zip: | PORTLAND, OR 972085136 |
| Phone: | (737) 233-1465 |

Backflow Test

| Initial Test | DCVA | |
|--------------|----------------|----------------|
| | Check Valve #1 | Check Valve #2 |
| | 2 PSID | 2 PSID |

Repairs

Test After Repairs

| | | | |
|-------------------|--------------|------------------------------|--------|
| Test Date: | Jun 25, 2024 | Backflow Test Status: | Passed |
|-------------------|--------------|------------------------------|--------|

Tester Information

The backflow technician listed below has previously certified that the information on this report was true and correct on the date of this test.

| | |
|-----------------------------|-----------------|
| Backflow Technician: | WEYANT, BRADLEY |
| License: | BP0016935 |
| Gauge Serial Number: | 09231317 |