Backflow Prevention Assembly Test Details

Special Services Division



Test and Maintenance Report

Water System ID# 2270001

Phone: (512) 972-1060 FAX: (512) 972-1260



3907 South Industrial DR Austin, TX 78744-1070

	*** Test records must	be kept by the customer for at least three years **	*	
	Backf	low Assembly Information		
Serial Number:	88805C	Manufacturer:	APOLLO/CONBRACO	
Model:	DC4A	Size:	1	
Service Address:		12320 DAIRYWORK RD 786	510	
Assembly location on the property:		FRONT LEFT AT THE METER		
Reason the assembly is installed:		IRRIGATION W/ CITY POTABLE WATER		
Is this assembly installed to code requ	irements?	Yes		
	(Customer Information		
Property Owner / Agent:		HOME OWNER	HOME OWNER	
Mailing Address:		12320 DAIRYWORK RD		
City / State / Zip:	BUDA, TX 78610			
Phone:				
		Backflow Test		
	DCVA			
Initial Test		Check Valve #1	Check Valve #2	
		2.2 PSID	2 PSID	
Repairs				
Test After Repairs				
Test Date:		Jul 1, 2024		
Backflow Test Status:		Passed		
		Tester Information		
The backflow technician listed below	has previously certifie	d that the information on this report wa	as true and correct on the date of this test.	
Backflow Technician:		STEVENSON, SCOTT		
License:	BP0017507			
Gauge Serial Number:	06163433			