Service Address	Hazard/CCID: 4					
* Location: Front right - 15' from the meter - right sode of the driveway						
1433 Blue Oak Blvd Meter#: Serial #: Check if						
SAN MARCOS, TX 78666 LID/Service:					82906C	
		Account #:	Ма	anufacturer:	Apollo	
Site Use: Hazard:			Mo	odel:	□ DC4A	
Mailing Address			Ту	/pe:	Daubla Chack	
1433 Blue Oak Blvd					Double Check	
San Marcos, Texas 78666				ze:	<u> </u>	
Orientation:						
Protection:					U	
	Irrigation - City Potable					
Test Due No Later than: Existing Removed Removed Commercial Industrial Residential Municipal Domestic Irrigation Fire						
Reduced Pressure Principle Assembly						
Double Check V		ve Assembly		Pı	PVB/SVB	
	Check Valve #1	Check Valve #2	Relief Valve	Air Inlet	Check Valve	
nitial Test	Leaked	Leaked \Box		Did not open		
Date 07/17/24	Closed Tight	Closed Tight	Did not open		s Leaked	
Time 9:06 am Pass Fail	Held at 2.0 PSID	Held at 2.2 PSID	Opened at PSID	No Opened at PS	SID Held atPSID	
Repairs	Cleaned					
Dota	Rubber Kit Rebuild					
Date	Replaced					
Time Final Test	Other	<u> </u>	<u> </u>	1	<u> </u>	
Date	Closed Tight	Closed Tight		Opened Fully		
Time						
Pass Fail	Held at PSID	Held at PSID	Opened at PSID	Opened at PS	SID Held at PSID	
Air Gap	Date	Time	Diameter	Separation	Pass	
Comments: Yes No						
					Proper Installation RV Exercised	
I certify all information on this report is true & accurate, acknowledging that incomplete reports will not be accepted.					#2 Shutoff Closed Service Restored	
Tester Scott Stevenson Signature Scott Stevenson						
Certification # BP0017507 Expire 12/19/25 Phone 512					Line Pressure	
Test Kit Serial #		Calibration Date 10/11/2023			Meter Reading	
Company Safety Plus Services, LLC Phone 512-300-9659					Test Results Pass 	
Company Pnone Pnone Pnone						



Submit completed Test Report:

630 E HOPKINS ST

SAN MARCOS TX 78666 512-393-8008 Fax: SODONNELL@SANMARCOSTX.GOV