CITY OF PFLUGERVILLE 210-B EAST PECAN STREET PHONE: (512) 990-6300

FAX: (512) 990-4374



BUILDING DEPARTMENT PO BOX 589 / 78691 PFLUGERVILLE, TEXAS 78660

BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

The following fo A signed and dat							E THIS REP	ORT IN	METER .	BOX	
	П	LEGA	L OR INCOM	IPLE 1	TE REPORTS V	VILL NO	T BE ACCE	PTED	***		
RESIDENTIAL Is the assembly in		CO rdance	MMERCIAL with manufactu	irer rec	commendations a	nd/or loca	al codes?	es	Santa		
BACKFLOW ASSEMBLY INFORMATION OF THE SERVICE OF THE			Manufacturer Apollo				_ModelD	CYA		_Size_/	
Occupant/Busine	ss Name										
Physical Address	15113	311/c	Bilar	SA.		iš .					
Physical Address Assembly Location	on on Property	8'0	Pest Mes	ler							
Purpose of Assen											
CUSTOMER INFO	Agent										
Mailing Address 15113 C			Ple Offer St Bldg. Zip Code						Suite#		
City Pelmenne			State VX				Zip	Code	ode_7866c		
The backflow pre operating within	acceptable para Redu Doul Press	meters. iced Proble Che sure Va	essure Principle ck Valve cuum Breaker	TYP	E OF ASSEMB Reduc Doubl	LY ed Pressu e Check I Resistant l	re Principle De Detector Pressure Vacuu	etector im Breaker			
	CHECK	VALVE ASSEMBI	Dank Sala at 1 a sta		A VID PAIR FOR		CHECK HATTE				
	1 ST CHECK		2 ND CHECK		RELIEF VALVE		AIR INLET		CHECK VALVE		
INITIAL TEST	Held at 1.4 Closed Tight Leaked	psid	Held at 1,8 Closed Tight Leaked	psid	Opened at Did not open	psid	Opened at Did not open	psid	Held at Leaked	psid	
TEST AFTER REPAIRS	Held at Closed Tight	psid	Held at Closed Tight	psid	Opened at	psid	Opened at	psid	Held at	psid	
REPAIRS AND MATERIALS USED											
Test gauge used:	ا: Make/Model	latts	TK-99 E		SN:	749	<u>97</u> c	alibration l	Date: 1/19	1/23	
Remarks: The above is cert	ified to he true	at the	time of testing								
CERTIFICATION					GAUGE SERIA	J.# 5	74997				
PHONE (511)					LOW TECHNIC		Thomas	Mone	•		
DATE 10/13/	/	Pr			ICIAN'S SIGNA	S20	Romp	10	_/		
TEST RECORDS	MUST BE KEP	T FOR				7	NUFACTURE	'S REPLA	CEMENT P	ARTS.	