City of Georgetown - Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly tested for recordkeeping *purposes:

	City of Georgetown PO Box 1430 Georgetown, Texas 786	Box 1430		S ID: tact Name: ne Number:	2460001 Water Regulatory 512-930-3640
			BPAT Inform	nation	
Company Name: Tester Name: Address:	Safewater Backflow and Brad Weyant 609 E 50TH AUSTIN, Texas 78751	E 50TH		ne Number: ail Address: ense Number: ense Expiratior	5126059790 brad@safewateratx.com BP0016935 1: 12/3/2024
	Location Informati	on			Contact Information
Property Type: Business Name: Property Address:	Residential 202 Lariat Loop Liberty Hill, TX 78642	ariat Loop			202 Lariat Loop Liberty Hill, TX 78642
			Backflow Infor	mation	
The backflow preventior	assembly detailed below h	as been tested and r	maintained as rec	uired by comm	ission regulations and is certified to be operating within
Backflow Method: Main Assembly Manuf Location: Hazard Type ****:	Double Check acturer: Apollo Left front yard 5 feet fror Irrigation - Non Chemica	Model:	DC4A	Size: 1	Serial Number: 64367C
		Ba	ackflow Test In	formation	
-	Passed New Installation ed in accordance with ma			or local codes	? Yes
-	ed on a non-potable water			00004047	D.1. T. 1. 16. A
Differential pressure gauge used:	MidWest 845-5 (potable)	:	Serial Number:	09231317	Date Tested for Accuracy:3/14/2024
		Double Check Valve			
	Check V	alve #1	Check Valve	e #2	
Initial Test Date: 6/5/2024 Time: 11:35 AM	Held at 1.8 PSID		ld at 1.9 PSID ClosedTight Leaked		
Repairs and Materials Used					
Repair Details					
Test After Repa	rs Held at 0 PSID				
		1	Remark	S	

The above is certified to be true at the time of testing. * TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS [30 TAC 290.46(B)] ** USE ONLY MANUFACTURER'S REPLACEMENT PARTS *** 2nd Check: Numeric reading required for double check valve only. **** Indicates additional information not present on the standard TCEQ report