



**Test and Maintenance Report**

Water System ID# 2270001

Special Services Division  
 3907 South Industrial DR  
 Austin, TX 78744-1070

Phone: (512) 972-1060  
 FAX: (512) 972-1260



\*\*\* Test records must be kept by the customer for at least three years \*\*\*

**Backflow Assembly Information**

<b>Serial Number:</b>	88794C	<b>Manufacturer:</b>	APOLLO/CONBRACO
<b>Model:</b>	DC4A	<b>Size:</b>	1
<b>Service Address:</b>	3013 CHENNAULT ST 78723		
<b>Assembly location on the property:</b>	CENTER FRONT YARD 15 FEET FROM METER - RIGHT OF SIDEWALK		
<b>Reason the assembly is installed:</b>	IRRIGATION W/ CITY POTABLE WATER		
<b>Is this assembly installed to code requirements?</b>	Yes		

**Customer Information**

<b>Property Owner / Agent:</b>	EMPIRE
<b>Mailing Address:</b>	
<b>City / State / Zip:</b>	
<b>Phone:</b>	

**Backflow Test**

Initial Test	DCVA	
	Check Valve #1	Check Valve #2
	1.8 PSID	2 PSID
<b>Repairs</b>		
<b>Test After Repairs</b>		
<b>Test Date:</b>	Jul 9, 2024	
<b>Backflow Test Status:</b>	Passed	

**Tester Information**

The backflow technician listed below has previously certified that the information on this report was true and correct on the date of this test.

<b>Backflow Technician:</b>	WEYANT, BRADLEY
<b>License:</b>	BP0016935
<b>Gauge Serial Number:</b>	09231317