



3812 Eok Lane • Austin, Tx 78734  
 Tel: 512-266-1111 • Fax: 512-266-2790

**Water and Wastewater Utility Cross Connection Section  
 Test and Maintenance Report  
 PWSID #2270027**

Date: 7/17/2024

Residential  Commercial

New Installation   
 Replacement   
 Annual Test

Fax (512-266-2790) or email completed form: Residential: ncardoso@wcid17.org Commercial: adufek@wcid17.org

**Results must be submitted within 5 days. Illegible or incomplete reports will not be accepted.**

<b>Backflow Assembly Information</b>		Please Print	
Serial Number: <u>59010C</u>	Manufacturer: <u>Apollo</u>	Model <u>RP4A</u>	Size: <u>1"</u>
Occupant/Business Name: <u>Farooq Muhammad Umar &amp; Sara Akhund</u>			
Physical Address: <u>309 Golden Bear Dr. Lakeway, TX 78738</u>			
Assembly Location on Property: <u>Left front yard 5 from meter</u>			
Reason the assembly is installed: <u>Irrigation with OSSF</u>			

**TYPE OF ASSEMBLY:**

- Reduced Pressure Principle
- Double Check Valve
- Pressure Vacuum Breaker
- Reduced Pressure Principle-Detector
- Double Check - Detector
- Spill-Resistant Pressure Vacuum Breaker

	Reduced Pressure Principle Assembly			Pressure Vacuum Breaker	
	Double Check Valve Assembly		Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check			
Initial Test	Held at <u>7.4</u> psid Closed Tight <input checked="" type="checkbox"/> Leaked <input type="checkbox"/>	Held at _____ psid Closed Tight <input checked="" type="checkbox"/> Leaked <input type="checkbox"/>	Opened at <u>2.7</u> psid Did not open <input type="checkbox"/>	Opened at _____ psid Did not open <input type="checkbox"/>	Held at _____ psid Leaked <input type="checkbox"/>
Repairs and Materials Used					
Test After Repair	Held at _____ psid Closed Tight <input type="checkbox"/>	Held at _____ psid Closed Tight <input type="checkbox"/>	Opened at _____ psid	Opened at _____ psid	Held at _____ psid

The above is certified to be true? Yes Is this assembly installed in accordance with Local Codes? Yes

**FINAL BACKFLOW TEST STATUS** Pass  Fail

Test gauge used: Make/Model MidWest 845 SN: 09231317 Calibration Date: 3/14/2024

Remarks: \_\_\_\_\_

Company Name: Safewater Backflow  
 Address: PO Box 4002 Austin, TX 78765  
 Phone #: 512-605-9790

Backflow Technician (print) Brad Weyant  
 Certified Tester (Signature)   
 Cert. Tester No. 7/18/2024