## City of Georgetown - Backflow Prevention Assembly Test and Maintenance Report The following form must be completed for each assembly tested for recordkeeping \*purposes: PWS ID: 2460001 City of Georgetown Water Regulatory PO Box 1430 **Contact Name:** 512-930-3640 Georgetown, Texas 78626 **Phone Number: BPAT Information** 512-563-8762 **Phone Number:** Company Name: L Sinclair Services, Inc. Email Address: lss@austin.rr.com Tester Name: Lewis Sinclair License Number: BP0002815 1307 Machado Road Address: Cedar Park, Texas 78613 License Expiration: 2/12/2026 Contact Information Company Name: Residential **Property Type: Contact Name: Business Name:** Mailing Address: 328 Terra Manor Trl 328 Terra Manor Trl **Property Address:** Georgetown, TX 78628 Georgetown, TX 78628 Phone Number: Email Address: Backflow Information The backflow prevention assembly detailed below has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters. **Backflow Method: Double Check Valve** Serial Number: HG61708 Model: 850 Size: 1 Main Assembly Manufacturer: Febco Location: 10' ENE of meter Hazard Type \*\*\*\*: Irrigation - Non Chemical Backflow Test Information **Test Result:** Passed Reason for Test: New Installation Is the assembly installed in accordance with manufacturers recommendations and/or local codes? Yes Is the assembly installed on a non-potable water supply (auxiliary)? No 3/16/2023 **Date Tested for Accuracy:** Serial Number: 03162474 Differential pressure Bac-Flo Bac-Flo 3 (potable) gauge used: **Double Check Valve** Check Valve #2 Held at 2.7 PSID Held at 2.8 PSID ✓ ClosedTight ✓ ClosedTight Leaked Leaked Repairs and Materials Used

Remarks

Held at 0 PSID

Closed Tight

Supply line pressure 100 psi

Held at 0 PSID

Closed Tight