City of Georgetown - Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly	y tested for recordkeeping *purposes:
--	---------------------------------------

City of Georgetown

PO Box 1430

Georgetown, Texas 78626

PWS ID:

2460001

Contact Name: Phone Number: Water Regulatory 512-930-3640

BPAT Information

Company Name: Tester Name:

L Sinclair Services, Inc. Lewis Sinclair

Address:

1307 Machado Road

Phone Number: Email Address:

512-563-8762 lss@austin.rr.com

License Number: License Expiration: BP0002815 2/12/2026

Cedar Park, Texas 78613

Property Type:

Residential

Business Name: Property Address:

5612 Sean Paul Ln

Georgetown, TX 78628

Company Name:

Contact Name:

Mailing Address:

5612 Sean Paul Ln Georgetown, TX 78628

Phone Number:

Email Address:

Backflow Information

The backflow prevention assembly detailed below has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters.

Backflow Method:

Double Check Valve

Main Assembly Manufacturer: Apollo Model: DC4A

Size: 1

Serial Number: 82352C

Location:

9' N of meter

Hazard Type ****:

Irrigation - Non Chemical

Test Result:

gauge used:

Passed

Reason for Test:

New Installation

Is the assembly installed in accordance with manufacturers recommendations and/or local codes? Yes

Is the assembly installed on a non-potable water supply (auxiliary)? No

Differential pressure

Mid-West 845-3 (potable)

Serial Number: 10200408

Date Tested for Accuracy:

2/27/2024

	Double Check Valve	
	Check Valve #1	Check Valve #2
Initial Test Date: 5/2/2024 Fime: 12:40 PM	Held at 2 PSID ✓ ClosedTight Leaked	Held at 1.9 PSID ☑ ClosedTight ☐ Leaked
Repairs and Materials Used		
Repair Details		
Test After Repairs	Held at 0 PSID	Held at 0 PSID Closed Tight

^{**} USE ONLY MANUFACTURER'S REPLACEMENT PARTS

^{*** 2}nd Check: Numeric reading required for double check valve only.