

## **Test and Maintenance Report**

Water System ID# 2270001

Phone: (512) 972-1060 FAX: (512) 972-1260



Special Services Division 3907 South Industrial DR Austin, TX 78744-1070

\*\*\* Test records must be kept by the customer for at least three years \*\*\*

	Test records mus	st be kept by the customer for at least three years		
	Back	flow Assembly Information		
Serial Number:	85521C	Manufacturer:	APOLLO/CONBRACO	
Model:	DC4A	Size:	1	
Service Address:		7416 BOYD HAVEN DR 78744	1	
Assembly location on the property:		RIGHT FRONT YARD 10 FEET FROM METER		
Reason the assembly is installed:		IRRIGATION W/ CITY POTABLE WATER		
Is this assembly installed to code requirements?		Yes		
		Customer Information		
Property Owner / Agent:		TAYLOR MORRISON OF TEXA	TAYLOR MORRISON OF TEXAS INC	
Mailing Address:				
City / State / Zip:				
Phone:				
		Backflow Test		
		DCVA		
Initial Test		Check Valve #1	Check Valve #2	
		2.3 PSID	2.1 PSID	
Repairs				
Test After Repairs				
Test Date:		May 28, 2024		
Backflow Test Status:		Passed		
		Tester Information		
The backflow technician listed b	below has previously certifi	ed that the information on this report was	true and correct on the date of this test	
Backflow Technician:		WEYANT, BRADLEY		
License:		BP0016935		
Gauge Serial Number:		09231317		