Service Address	Hazard/CCID:	Backflow Prevention Assembly Test Report			
* Location: 1005 Teakmill Trail San Marcos, TX 78666					
SAN MARCOS, T	X 78666	Meter#: 96225649 LID/Service:) Se	erial #: Check if Cor	rect Corrections
		Account #:	M		Apollo
Site Use: Hazard: Irrigation			M	odel:	ŎDC4A
Mailing Address			Ту	/pe:	▼ DCVA
1005 Teakmill Trail			Si	70.	
San Marcos, TX 78666			O	Orientation:	
			Pr	-otootion.	Nrrigation - Low
Tool Buo No Eutor trium	New Re	placed L	Industrial Residentia	ıl ⊠ Municipal □ Dor	mestic Irrigation 🛛 Fire 🗌
	Reduced Pressure Principle Assembly				
Double Check V		ve Assembly		PVB/SVB	
	Check Valve #1	Check Valve #2	Relief Valve	Air Inlet	Check Valve
Initial Test Date 10-31-24	Leaked Closed Tight	Leaked ☐ Closed Tight ☒	Did not open	Did not open Opened Fully Yes	
Time <u>10:45AM</u> Pass ⊠ fail □	Held at 1.7 PSID	Held at 1.9 PSID	Opened at PSID	No l	
Repairs	Cleaned				
Date	Rubber Kit L				
Time	Replaced Other				
Final Test Date	Closed Tight	Closed Tight		Opened Fully	
Time Pass ☐Fail ☐	Held at PSID	Held at PSID	Opened at PSID	Opened at PSID	Held at PSID
Air Gap	Date	Time	Diameter	Separation	Pass
Comments:				Pro	Yes No oper Installation
					oper Installation / Exercised Shutoff Closed
Tester Signature Signatur					
BP0016935 Certification #		Expire 12/3/2024 Phone 5126059790			ne Pressureeter Reading 4072.69
Test Kit Serial # Ca					Test Results
Company Safewater Backflow Phone 5126059790 Pass ☒ Fail					



Submit completed Test Report:

SAN MARCOS TX 78666 512-393-8008 Fax:

SODONNELL@SANMARCOSTX.GOV