



Test and Maintenance Report

Water System ID# 2270001

Special Services Division
3907 South Industrial DR
Austin, TX 78744-1070

Phone: (512) 972-1060
FAX: (512) 972-1260



*** Test records must be kept by the customer for at least three years ***

Backflow Assembly Information

Serial Number:	85614C	Manufacturer:	APOLLO/CONBRACO
Model:	DC4A	Size:	1
Service Address:	2711 W PECAN ST 78660		
Assembly location on the property:	1519 IBERVILLE LEFT FRONT YARD 5 FEET FROM METER		
Reason the assembly is installed:	IRRIGATION W/ CITY POTABLE WATER		
Is this assembly installed to code requirements?	Yes		

Customer Information

Property Owner / Agent:	ENCLAVE AT SARAHS CREEK COA INC
Mailing Address:	11950 JOLLYVILLE RD
City / State / Zip:	AUSTIN, TX 78759
Phone:	(512) 502-7036

Backflow Test

Initial Test	DCVA	
	Check Valve #1	Check Valve #2
	2.1 PSID	2.1 PSID
Repairs		
Test After Repairs		
Test Date:	Aug 29, 2024	
Backflow Test Status:	Passed	

Tester Information

The backflow technician listed below has previously certified that the information on this report was true and correct on the date of this test.

Backflow Technician:	WEYANT, BRADLEY
License:	BP0016935
Gauge Serial Number:	09231317