

## City of Georgetown - Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly tested for recordkeeping \*purposes:

City of Georgetown  
 PO Box 1430  
 Georgetown, Texas 78626

**PWS ID:** 2460001  
**Contact Name:** Water Regulatory  
**Phone Number:** 512-930-3640

### BPAT Information

**Company Name:** Safety Plus Services, LLC.  
**Tester Name:** Scott Stevenson  
**Address:** 102 Wonder World Drive, Suite #304-522  
 San Marcos, Texas 78666

**Phone Number:** 512-300-9659  
**Email Address:** scott@safetyplusservices.com  
**License Number:** BP0017507  
**License Expiration:** 12/19/2025

### Location Information

**Property Type:** Residential  
**Business Name:**  
**Property Address:** 253 Bluff Creek Ln  
 Andice, TX 78628

### Contact Information

**Company Name:**  
**Contact Name:**  
**Mailing Address:** 253 Bluff Creek Ln  
 Andice, TX 78628  
**Phone Number:**  
**Email Address:**

### Backflow Information

The backflow prevention assembly detailed below has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters.

**Backflow Method:** Double Check Valve  
**Main Assembly Manufacturer:** Apollo      **Model:** DC4A      **Size:** 1      **Serial Number:** 53490C  
**Location:** At meter  
**Hazard Type \*\*\*\*:** Irrigation - Non Chemical

### Backflow Test Information

**Test Result:** Passed  
**Reason for Test:** New Installation

**Is the assembly installed in accordance with manufacturers recommendations and/or local codes?** Yes

**Is the assembly installed on a non-potable water supply (auxiliary)?** No

**Differential pressure gauge used:** BacFlo Unlimited Bac Flo 5 (potable)      **Serial Number:** 06163433      **Date Tested for Accuracy:** 10/11/2023

|   | Double Check Valve   |  |
|---|--|--|
|   | Check Valve #1   | Check Valve #2   |
| <b>Initial Test</b><br>Date: 6/10/2024<br>Time: 3:26 PM | Held at 1.6 PSID<br><input checked="" type="checkbox"/> ClosedTight<br><input type="checkbox"/> Leaked | Held at 2.2 PSID<br><input checked="" type="checkbox"/> ClosedTight<br><input type="checkbox"/> Leaked |
| <b>Repairs and Materials Used</b>                       |  |  |
| <b>Repair Details</b>                                   |  |  |
| <b>Test After Repairs</b>                               | Held at 0 PSID<br><input type="checkbox"/> Closed Tight  | Held at 0 PSID<br><input type="checkbox"/> Closed Tight  |

### Remarks

The above is certified to be true at the time of testing.  
 \* TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS [30 TAC 290.46(B)]  
 \*\* USE ONLY MANUFACTURER'S REPLACEMENT PARTS  
 \*\*\* 2nd Check: Numeric reading required for double check valve only.  
 \*\*\*\* Indicates additional information not present on the standard TCEQ report