Service Address	Hazard/CCID:		Backflow Prevent	•	est Report
* Location: 308 Chas Meter#: 96224810 SAN MARCOS, TX 78666 LID/Service: Account #:			erial #: Check if Correct Corrections 98274C		
Site Use:				Apollo Indel: Apollo Apollo Apollo	
Hazard: Irrigation <u>Mailing Address</u>			Ту	ype:	
308 Chaste To			Siz	ize:	1"
San Marcos, TX 78666			Or	rientation:	Horizontal
			Pr-	rotection:	rrigation - Low
Test Due No Later than: Existing					
Reduced Pressure Principle Assembly					!
Double Check Valve				PVB/SVB	
	Check Valve #1	Check Valve #2	Relief Valve	Air Inlet	Check Valve
nitial Test Date 10-29-24	Leaked Closed Tight	Leaked ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	Did not open	Did not open Opened Fully Yes No	Leaked
Time <u>12:30PM</u> Pass ⊠ fail □	Held at 1.7 PSID	Held at 2.0 PSID	Opened at PSID	Opened at PSID	Held at PSID
Repairs Date Time	Cleaned				
Final Test Date	Closed Tight	Closed Tight		Opened Fully	
Time PassFail	Held at PSID	Held at PSID	Opened at PSID	Opened at PSID	Held at PSID
Air Gap	Date	Time	Diameter	Separation	Pass Fail
Comments:					er Installation Kercised Wutoff Closed Yes No Yes No X X X X X X X X X X
I certify all information on this report is true & accurate, acknowledging that incomplete reports will not be accepted. Service Restored Service Restored					
BP0016935 Certification #		Line Pressure 60 Meter Reading 1863.55			
Test Kit Serial # 09231317 Calibration Date 3/14/2024					Test Results
Company Safewater Backflow Phone 5126059790 Pass ☑ Fail ☐					



Submit completed Test Report: 630 E HOPKINS ST

SAN MARCOS TX 78666 512-393-8008 Fax: SODONNELL@SANMARCOSTX.GOV