

Test and Maintenance Report

Water System ID# 2270001

Phone: (512) 972-1060 FAX: (512) 972-1260



Special Services Division 3907 South Industrial DR Austin, TX 78744-1070

*** Test records must be kept by the customer for at least three years ***

	Backflow Ass	embly Information		
Serial Number:	85527C	Manufacturer:	APOLLO/CONBRACO	
Model:	DC4A	Size:	1	
Service Address:		6400 COWMAN WAY 78747		
Assembly location on the property:		RIGHT FRONT CORNER OF HOUSE		
Reason the assembly is installed:		IRRIGATION W/ CITY POTABLE WATER		
Is this assembly installed to code requiren	ments?	Yes		
	Custome	er Information		
Property Owner / Agent:		EMPIRE		
Mailing Address:				
City / State / Zip:				
Phone:				
	Back	kflow Test		
		DCVA		
Initial Test	Check Va		Check Valve #2	
	1.9 PS	SID	2 PSID	
Repairs				
Test After Repairs				
Test Date:	May 31, 2024			
Backflow Test Status:		Passed		
	Tester	Information		
The backflow technician listed belo			ue and correct on the date of this test	
Backflow Technician:	WEYANT, BRADLEY			
	BP0016935			
License:		BP0016935		