

Test and Maintenance Report

Water System ID# 2270001

Phone: (512) 972-1060 FAX: (512) 972-1260



Special Services Division 3907 South Industrial DR Austin, TX 78744-1070

*** Test records must be kept by the customer for at least three years ***

| | Backf | low Assembly Information | | |
|---|------------------------------|----------------------------------|--|--|
| Serial Number: | 82666C | Manufacturer: | APOLLO/CONBRACC | |
| Model: | DC4A | Size: | 1 | |
| Service Address: | | 6410 COWMAN WAY 78747 | | |
| Assembly location on the property: | | LEFT FRONT CORNER OF HOUSE | | |
| Reason the assembly is installed: | | IRRIGATION W/ CITY POTABLE WATER | | |
| Is this assembly installed to code requir | rements? | Yes | | |
| | C | Customer Information | | |
| Property Owner / Agent: | | EMPIRE | | |
| Mailing Address: | | | | |
| City / State / Zip: | | | | |
| Phone: | | | | |
| | | Backflow Test | | |
| | | DCVA | | |
| Initial Test | | | Check Valve #2 | |
| | | 2.2 PSID | 2.1 PSID | |
| Repairs | | 2.21510 | 2.11310 | |
| Test After Repairs | | | | |
| Test Date: | | May 28, 2024 | | |
| Backflow Test Status: | | Passed | | |
| | | Tester Information | | |
| The backflow technician listed by | elow has previously certifie | | true and correct on the date of this test. | |
| Backflow Technician: | | WEYANT, BRADLEY | | |
| License: | | BP0016935 | | |
| Gauge Serial Number: | | 09231317 | | |