

4050 FM 1660 Hutto, Texas 78634 512-759-1286 Fax 512-759-2983

## BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

PWS I.D: 2460022

MAILING ADDRESS\_100 Lansing Road Hutto, TX 78634\_\_\_\_\_ CONTACT PERSON \_\_Taylor Morrison \_\_\_\_\_ LOCATION OF SERVICE 100 Lansing Road Hutto, TX 78634\_\_\_\_\_ INSPECTION DATE \_10/11/2024\_2:40PM\_\_\_\_\_

The backflow prevention assembly detailed below has been tested and maintained as required by TCEQ regulations and is certified to be operating within acceptable parameters.

() Reduced Pressure ZONE

(X) Double Check Valve

() Pressure Vacuum Breaker

- () Reduced Pressure Principle-Detector
- () Double Check-Detector
- () Spill-Resistant Pressure Vacuum Breaker

Manufacturer: Apollo\_\_\_\_\_

Model # DC4A\_\_\_\_\_ Serial # 97817C\_\_\_\_\_

Location of device Right front yard 5 feet from meter \_\_\_\_\_

Is the assembly installed in accordance with manufacturer recommendations and/or local codes? Yes\_\_\_\_\_

	Reduced Pressure Principle Assembly			Pressure Vacuum Breaker	
	Double Check Valve Assembly		Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check		Opened at psid	Held at psid
Initial Test	Held at 1.5 Psi	Held at 1.9 psid	Opened at psid	Did not Open 🛛	Leaked 🗆
	Closed Tight X Leaked □	Closed X Tight Leaked □	Did not open □		
Repairs and Materials Used					
Test After	Held at ps Closed Tight □	d Held at psid Closed Tight □	Opened at psid	Opened at psid	Held At psid
Repair					

The above is certified to be true at the time of testing,

Test gauge used: Make / Model Mid West 845

Firm Name Safewater Backflow

SN: 09231317

Certified Tester: Brad Weyant

Calibration Date:3/14/2024

Firm Address PO Box 4002 Austin, TX 78765

Cert. Tester No: BP0016935

Firm Phone # 512-605-9790

- TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS \*\* USE ONLY MANUFACTURER'S REPLACEMENT PARTS