

4050 FM 1660 Hutto, Texas 78634 2983 512-759-1286 Fax 512-759-

BACI PWS I.D: 2460022	KFLOW PREVENTION	ON ASSEMBLY T	EST AND MAINTEN	ANCE REPORT	
MAILING ADDRESS_	100 Makinaw St. Hutto,	TX 78634			
CONTACT PERSON	Taylor Morrison	 			
LOCATION OF SERV	ICE 100 Makinaw St. ⊢	lutto, TX 78634			
INSPECTION DATE	_6/14/2024_11:40AM				
•	ion assembly detailed bating within acceptable		d and maintained as red	quired by TCEQ regula	ations and
		TYPE OF A	ASSEMBLY		
() Reduced Pressure ZONE			() Reduced Pressure Principle-Detector		
(X) Double Check Valve		() Double Check-Detector			
() Pressure Vacuum Breaker		() Spill-Resistant Pressure Vacuum Breaker			
Manufacture	er: Apollo				
Model # DC4A Serial # 53063C					
		_	mendations and/or local		
	Reduced	Pressure Principle A	ssembly	Pressure Vacuum Breaker	
	Double Check Valve Assembly		Relief Valve	Air Inlet Check Valve	
	1st Check	2nd Check		Opened at psid	Held at psid
Initial Test	Held at 1.9 Psi	Held at 2.0 psid	Opened at psid	Did not Open	Leaked
	Closed Tight X	Closed Tight X	Did not open		†
	Leaked	Leaked	·		
Repairs and Materials Used					
Test After	Held at psid Closed Tight □	Held at psid Closed Tight □	Opened at psid	Opened at psid	Held At psid
Repair					
The above is certific	ed to be true at the time	of testing,			
Test gauge used: M	lake / Model Mid West	845 SN: 092	231317 Calibrat	tion Date:3/14/2024	
Firm Name Safewater Backflow Certified Tester: Brad Weyant					

- TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS ** USE ONLY MANUFACTURER'S REPLACEMENT PARTS

Cert. Tester No: BP0016935

Firm Address PO Box 4002 Austin, TX 78765

Firm Phone # 512-605-9790