

4050 FM 1660 Hutto, Texas 78634 512-759-1286 Fax 512-759-2983

BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

PWS I.D: 2460022 MAILING ADDRESS 103 Beartooth Hutto, TX 78634 CONTACT PERSON ______ Taylor Morrison____ LOCATION OF SERVICE 103 Beartooth Hutto, TX 78634_____ INSPECTION DATE _12/10/2024_10:15AM_____

The backflow prevention assembly detailed below has been tested and maintained as required by TCEQ regulations and is certified to be operating within acceptable parameters.

TYPE OF ASSEMBLY

()

() Reduced Pressure Principle-Detector

Spill-Resistant Pressure Vacuum Breaker

() Double Check-Detector

Reduced Pressure ZONE ()

(X) Double Check Valve

Pressure Vacuum Breaker ()

Manufacturer: Apollo_____

Model # DC4A Serial # 89040C

Location of device Left front yard 5 feet from meter

Is the assembly installed in accordance with manufacturer recommendations and/or local codes? Yes____

	Reduced Pressure Principle Assembly			Pressure Vacuum Breaker	
	Double Check Valve	Assembly	Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check		Opened at psid	Held at psid
Initial Test	Held at 2.1	Held at psid 2.2	Opened at psid	Did not Open 🛛	Leaked 🗆
	Closed Tight X Leaked □	Closed Tight X Leaked □	Did not open □		
Repairs and Materials Used					
Test After	Held at psid Closed Tight □	Held at psid Closed Tight □	Opened at psid	Opened at psid	Held At psid
Repair					

The above is certified to be true at the time of testing,

Test gauge used: Make / Model Mid West 845

Firm Name Safewater Backflow

SN: 09231317

Calibration Date:3/14/2024

Firm Address PO Box 4002 Austin, TX 78765

Certified Tester: Brad Weyant Cert. Tester No: BP0016935

Firm Phone # 512-605-9790

- TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS ** USE ONLY MANUFACTURER'S REPLACEMENT PARTS