

4050 FM 1660 Hutto, Texas 78634 2983 512-759-1286 Fax 512-759-

BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

PWS I.D: 2460022	, 1002111221 120	. ,
MAILING ADDRESS105 Beartooth Hutto, TX 786	634	
CONTACT PERSONTaylor Morrison		
OCATION OF SERVICE 105 Beartooth Hutto, 1	TX 78634	
NSPECTION DATE _12/10/2024_10:05AM		
The healflow provention accombly detailed heles	w has been tested as	ad maintained as required by TCFO requilations and
· · ·		nd maintained as required by TCEQ regulations and
s certified to be operating within acceptable par	ameters.	
	TYPE OF ASS	EMBLY
() Reduced Pressure ZONE	()	Reduced Pressure Principle-Detector
(X) Double Check Valve	()	Double Check-Detector
() Pressure Vacuum Breaker	()	Spill-Resistant Pressure Vacuum Breaker
Manufacturer: Apollo	_	
Model # DC4A	Serial # 85388C	
Location of device Right front yard 5 fe	et from meter	
s the assembly installed in accordance with man	nufacturer recommen	dations and/or local codes? Yes

	Reduced F	Pressure Principle A	Pressure Vacuum Breaker		
	Double Check Valve Assembly		Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check		Opened at psid	Held at psid
Initial Test	Held at 2.2	Held at psid 1.9	Opened at psid	Did not Open	Leaked
	Closed Tight X Leaked	Closed Tight X Leaked □	Did not open □		
Repairs and Materials Used					
Test After	Held at psid Closed Tight □	Held at psid Closed Tight □	Opened at psid	Opened at psid	Held At psid
Repair					

The above is certified to be true at the time of testing,

Test gauge used: Make / Model Mid West 845 SN: 09231317 Calibration Date:3/14/2024

Firm Name Safewater Backflow

Certified Tester: Brad Weyant

Firm Address PO Box 4002 Austin, TX 78765

Cert. Tester No: BP0016935

Firm Phone # 512-605-9790

- TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS ** USE ONLY MANUFACTURER'S REPLACEMENT PARTS