	Georgetown, TX 78628 Phone Number: Email Address: Backflow Information ention assembly detailed below has been tested and maintained as required by commission regulations and is certified to be operating within eters. Double Check Valve		
The following form mus	t be completed for each assembly teste	ed for recordkeeping *purposes:	
	City of Georgetown	PWS ID:	2460001
		Contact Name:	Water Regulatory
		Phone Number:	-
		BPAT Information	
Company Name:	L Sinclair Services, Inc.		512-563-8762
Tester Name:	Lewis Sinclair	Email Address:	Iss@austin.rr.com
Address:	1307 Machado Road	License Number:	BP0002815
	Cedar Park, Texas 78613	License Expiration:	2/12/2026
	Location Information		Contact Information
Property Type:	Residential		
Business Name:			
Property Address:		Mailing Address:	
	Georgetown, TX 78628	Phone Number:	Georgetown, TX 78628
		Email Address:	
acceptable parameters. Backflow Method: Main Assembly Manuf Location: Hazard Type ****: Test Result: Reason for Test:	Double Check Valve facturer: Apollo 4' W of meter Irrigation - Non Chemical Passed New Installation	Backflow Test Information	
-	lied in accordance with manufacturer lied on a non-potable water supply (a		res
Differential pressure gauge used:	Bac-Flo Bac-Flo 3 (potable)	Serial Number: 03162474	Date Tested for Accuracy: 3/16/2023
	Double Check Valve		
	Check Valve #1	Check Valve #2	
Initial Test	Held at 1.8 PSID	Held at 1.9 PSID	
Date: 11/20/2023	✓ ClosedTight	✓ ClosedTight	
Time: 1:35 PM	Leaked	Leaked	
Repairs and Materials Use			
Repair Detail	s		
Test After Repa	airs Held at 0 PSID	Held at 0 PSID	
	Closed Tight	Closed Tight	

Remarks

^{*** 2}nd Check: Numeric reading required for double check valve only.

^{****} Indicates additional information not present on the standard TCEQ report