

4050 FM 1660 Hutto, Texas 78634 2983 512-759-1286 Fax 512-759-

BACKFLOW PREVENTION PWS I.D: 2460022	N ASSEMBLY T	EST AND MAINTEN	IANCE REPORT			
MAILING ADDRESS_108 Lansing Road Hutto,	TX 7863/I					
CONTACT PERSONTaylor Morrison						
LOCATION OF SERVICE 108 Lansing Road						
INSPECTION DATE _10/11/2024_3:10PM						
The backflow prevention assembly detailed be is certified to be operating within acceptable		d and maintained as re	quired by TCEQ regula	ations and		
o solumou to 20 operating minim acceptable		A COEMPLY				
() Reduced Pressure ZONE		ASSEMBLY	Orinainla Datastar			
()			() Reduced Pressure Principle-Detector() Double Check-Detector			
() Pressure Vacuum Breaker		` '	ressure Vacuum Brea	ker		
() Hossare Vasaam Breaker		() Opin redoletane r	roccaro vacaam Broa			
Manufacturer: Apollo						
Model # DC4A	Serial # 940530	c				
Location of device Right front yard 5	feet from meter					
Is the assembly installed in accordance with n	nanufacturer recomr	mendations and/or local	codes? Yes			
Reduced F	Pressure Principle As	ssembly	Pressure Vac	uum Breake	r	
Double Check Valve Assembly		Relief Valve	Air Inlet Check Valve			
	j					
1st Check	2nd Check		Opened at psid	Held at	psid	
Initial Test Held at 2.1 Psi	Held at 1.7 psid	Opened at psid	Did not Open	Leaked		
Closed Tight X	Closed X Tight	Did not open		┪		
Leaked □	Leaked	•				
Repairs and Materials Used						
Held at psid	Held at psid	Opened at psid	Opened at psid	Held At	psid	
Test After Closed Tight	Closed Tight ['] □					
Repair						
The above is certified to be true at the time	of testing,					
	-					
Test gauge used: Make / Model Mid West	845 SN: 092	231317 Calibra	tion Date:3/14/2024			

- TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS ** USE ONLY MANUFACTURER'S REPLACEMENT PARTS

Cert. Tester No: BP0016935

Firm Address PO Box 4002 Austin, TX 78765

Firm Phone # 512-605-9790