

4050 FM 1660 Hutto, Texas 78634 2983 512-759-1286 Fax 512-759-

BAC PWS I.D: 2460022	KFLOW PREVENTI	ON ASSEMBLY T	EST AND MAINTEN	IANCE REPORT	
	112 Makinaw Hutto, TX 7	'8634			
	Taylor Morrison			_	
INSPECTION DATE	_7/1/2024_12:20PM				
	tion assembly detailed ating within acceptable		ed and maintained as re	quired by TCEQ regula	ations and
•	,		A COEMBLY		
TYPE OF ASSEMBLY					
Reduced Pressure ZONE (X) Double Check Valve			Reduced Pressure Principle-Detector Double Check-Detector		
() Pressure Vacuum Breaker		Spill-Resistant Pressure Vacuum Breaker			
() 11633	ule vacuulii bieakei		() Opin-Resistant i	ressure vacuum brear	(C)
Manufacture	er: Apollo				
Model # DC	4A	Serial # 53293	BC		
Location of	device Right front yard	5 feet from meter			
Is the assembly insta	lled in accordance with	manufacturer recom	mendations and/or local	codes? Yes	
	Reduced Pressure Principle Assembly			Pressure Vacuum Breaker	
	Double Check Valve Assembly		Delia (Valera	Air Inlot Charle Value	
-	Double Check Valv	e Assembly	Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check		Opened at psid	Held at psid
Initial Test	Held at 1.8	Held at 2.3 psid	Opened at psid	Did not Open	Leaked
	Psi			·	
İ	Closed Tight X	Closed Tight X	Did not open		†
	Leaked	Leaked	'		
Repairs and Materials Used					
	Held at psid	Held at psid	Opened at psid	Opened at psid	Held At psid
Test After	Closed Tight	Closed Tight	opened at pold	Opened at paid	riola At pala
Repair					
The above is certific	ed to be true at the tim	e of testing,			
	Make / Model Mid Wes		231317 Calibra	tion Date:3/14/2024	
Firm Name Safewater Backflow			Certified Tester: Brad Weyant		

- TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS ** USE ONLY MANUFACTURER'S REPLACEMENT PARTS

Cert. Tester No: BP0016935

Firm Address PO Box 4002 Austin, TX 78765

Firm Phone # 512-605-9790