## City of Kyle - Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly tested for recordkeeping \*purposes:

City of Kyle 1050002 520 E RR 150 **Contact Name:** Mickal Morrison Kyle, Texas 78640 Phone Number: 737-877-2927

**BPAT Information** 

**Company Name:** Safety Plus Services, LLC.

Scott Stevenson **Tester Name:** 

102 Wonder World Drive, Suite #304-522

San Marcos, Texas 78666

Phone Number: **Email Address:** 

scott@safetyplusservices.com

License Number: BP0017507 License Expiration: 12/19/2025

**Property Type:** Residential

**Business Name: Property Address:** 

Address:

119 Wood Thrush Run

Kyle, TX 78640

**Company Name:** Contact Name:

Highland Homes

512-300-9659

**Mailing Address:** 119 Wood Thrush Run

Kyle, TX 78640 Phone Number:

**Email Address:** 

The backflow prevention assembly detailed below has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters.

**Backflow Method: Double Check Valve** 

Main Assembly Manufacturer: Apollo Model: DC4A Size: 1 Serial Number: 98125C

Location: Front right - 5' from the meter Hazard Type \*\*\*\*: Irrigation - Non Chemical

**Test Result:** Passed New Installation Reason for Test:

Is the assembly installed in accordance with manufacturers recommendations and/or local codes? Yes

Is the assembly installed on a non-potable water supply (auxiliary)? No

Differential pressure gauge used:

BacFlo Unlimited Bac Flo 5 (potable)

Serial Number: 06163433

**Date Tested for Accuracy:** 

10/11/2023

	Double Check Valve	
	Check Valve #1	Check Valve #2
Initial Test	Held at 2 PSID	Held at 1.7 PSID
Date: 10/7/2024	✓ ClosedTight	✓ ClosedTight
Time: 2:10 PM	Leaked	Leaked
Repairs and Materials Used		
Repair Details		
Test After Repairs	Held at 0 PSID	Held at 0 PSID
	Closed Tight	Closed Tight

## Remarks

<sup>\*\*</sup> USE ONLY MANUFACTURER'S REPLACEMENT PARTS

<sup>\*\*\* 2</sup>nd Check: Numeric reading required for double check valve only. \*\*\*\* Indicates additional information not present on the standard TCEQ report