City of Georgetown - Backflow Prevention Assembly Test and Maintenance Report

City of Georgetown PWS ID: 2460001

PO Box 1430 Contact Name: Water Regulatory
Georgetown, Texas 78626 Phone Number: 512-930-3640

BPAT Information

The following form must be completed for each assembly tested for recordkeeping *purposes:

 Company Name:
 L Sinclair Services, Inc.
 Phone Number:
 512-563-8762

 Tester Name:
 Lewis Sinclair
 Email Address:
 Iss@austin.rr.com

 Address:
 1307 Machado Road
 License Number:
 BP0002815

Cedar Park, Texas 78613 License Expiration: 2/12/2026

Location Information Contact Informatio

Property Type: Residential Company Name:

Business Name: Contact Name:

Property Address: 1205 Cypress Paul Steet Mailing Address: 1205 Cypress Paul Steet

Georgetown, TX 78628

Phone Number:

Email Address:

Georgetown, TX 78628

Figure 1.25

Backflow Information

The backflow prevention assembly detailed below has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters.

Backflow Method: Double Check Valve

Main Assembly Manufacturer:ApolloModel:DC4ASize:1Serial Number:83331C

Location: 4' ENE of meter

Hazard Type ****: Irrigation - Non Chemical

Test Result: Passed

Reason for Test: New Installation

Is the assembly installed in accordance with manufacturers recommendations and/or local codes? Yes

Is the assembly installed on a non-potable water supply (auxiliary)? No

Differential pressure Mid-West 845-3 (potable) Serial Number: 10200408 Date Tested for Accuracy: 2/27/2024

gauge used:

	Double Check Valve	
	Check Valve #1	Check Valve #2
Initial Test Date: 6/17/2024 Time: 12:45 PM	Held at 2 PSID ☑ ClosedTight ☐ Leaked	Held at 2.1 PSID ☑ ClosedTight ☐ Leaked
Repairs and Materials Used		
Repair Details		
Test After Repairs	Held at 0 PSID Closed Tight	Held at 0 PSID

Remarks