## City of Georgetown - Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly tested for recordkeeping \*purposes:

	PO Box	Georgetown 1430 town, Texas 78626		PWS ID: Contact Name: Phone Number:	2460001 Water Regulatory 512-930-3640	
			BPAT I	nformation		
Company Name: Tester Name: Address:	Brad W 609 E 5	Safewater Backflow and Irrigation Brad Weyant 609 E 50TH AUSTIN, Texas 78751		Phone Number: Email Address: License Number: License Expiration:	5126059790 brad@safewateratx.com BP0016935 : 12/3/2024	
	Loca	ation Information			Contact Information	
Property Type: Business Name: Property Address:	Resider 124 Poo Liberty I			Company Name: Contact Name: Mailing Address: Phone Number: Email Address:	124 Poole Ln Liberty Hill, TX 78642	
			Backflow	Information		
The backflow preventior	assembly	detailed below has been t			ssion regulations and is certified to be operating within	
Backflow Method: Main Assembly Manuf Location: Hazard Type ****:	Right fro	Double Check Valve Apollo ont yard 5 feet from meter n - Non Chemical	Serial Number: 88849C			
Test Result:	Passed		Backflow I	est Information		
Reason for Test:		assed Iew Installation				
Is the assembly install	ed in acco	rdance with manufactur	ers recommendation	s and/or local codes?	? Yes	
Is the assembly install	ed on a no	on-potable water supply	(auxiliary)? No			
•		st 845-5 (potable)	Serial Num	ber: 09231317	Date Tested for Accuracy: 3/14/2024	
gauge used:	Г	Dei	uble Check Valve			
	h	Check Valve #1		v Valve #2		
Initial Test Date: 8/5/2024 Time: 1:20 PM Repairs and Materials Used	[	Held at 2.3 PSID	Held at 1.9 PS	iD		
Repair Details			I			
Test After Repairs		Held at 0 PSID	Held at 0 PSIE			
			Rei	marks		

The above is certified to be true at the time of testing. \* TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS [30 TAC 290.46(B)] \*\* USE ONLY MANUFACTURER'S REPLACEMENT PARTS \*\*\* 2nd Check: Numeric reading required for double check valve only. \*\*\*\* Indicates additional information not present on the standard TCEQ report