## Backflow Prevention Assembly Test Details

	Teste	nd Maintenan an Danaut		
STOL ALSA	Test and Maintenance Report         Water System ID# 2270001    Austin			
	Special Services Division 3907 South Industrial DR Austin, TX 78744-1070		e: (512) 972-1060 (: (512) 972-1260	
	*** Test records r	must be kept by the customer for at least three years	***	
	Ва	ckflow Assembly Information		
Serial Number:	88804C	Manufacturer:	APOLLO/CONBRACO	
Model:	DC4A	Size:	1	
Service Address:		12500 DAIRYWORK RD 78610		
Assembly location on the property:		FRONT LEFT - 3' FROM M	FRONT LEFT - 3' FROM METER	
Reason the assembly is installed:		IRRIGATION W/ CITY PO	IRRIGATION W/ CITY POTABLE WATER	
Is this assembly install	ed to code requirements?	Yes		
		Customer Information		
Property Owner / Agent:		HOME OWNER	HOME OWNER	
Mailing Address:		12500 DAIRYWORK RD	12500 DAIRYWORK RD	
City / State / Zip:	e / Zip: BUDA, TX 78610			
Phone:				
		Backflow Test		
		DCVA		
Initial Test		Check Valve #1	Check Valve #2	
		2 PSID	2.2 PSID	
Repairs				
Test After Repairs				
Test Date:		Jul 1, 2024		
Backflow Test Status:		Passed		
		Tester Information		
The backflow techn	ician listed below has previously cer	tified that the information on this report	was true and correct on the date of this test.	
Backflow Technician:	STEVENSON, SCOTT			
License:		BP0017507		
Gauge Serial Number:		06163433	06163433	