Backflow Prevention Assembly Test Details

Special Services Division

3907 South Industrial DR

Austin, TX 78744-1070



Test and Maintenance Report

Water System ID# 2270001

Phone: (512) 972-1060 FAX: (512) 972-1260



*** Test records must be kept by the customer for at least three years ***

		effects Appearable Tofe and the		
		flow Assembly Information		
Serial Number:	88594C	Manufacturer:	APOLLO/CONBRACO	
Model:	DC4A	Size:	1	
Service Address:		12700 BRAVE TENDERFOO	OT TRL 78610	
Assembly location on the property:		FRONT LEFT 6' FROM THE	FRONT LEFT 6' FROM THE METER	
Reason the assembly is installed:		IRRIGATION W/ CITY POTABLE WATER		
Is this assembly installed to code req	uirements?	Yes		
		Customer Information		
Property Owner / Agent:		NEW CONSTRUCTION	NEW CONSTRUCTION	
Mailing Address:	12700 BRAVE TENDERFOOT TRAIL			
City / State / Zip:		BUDA, TX 78610		
Phone:				
		Backflow Test		
		DCVA		
Initial Test		Check Valve #1	Check Valve #2	
		2.4 PSID	2.2 PSID	
Repairs				
Test After Repairs				
Test Date:		Dec 17, 2024		
Backflow Test Status:		Passed		
		Tester Information		
The backflow technician listed belo	w has previously certif	ied that the information on this report w	as true and correct on the date of this test	
Backflow Technician:		STEVENSON, SCOTT		
License:		BP0017507		
Gauge Serial Number:				