City of Georgetown - Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly tested for recordkeeping *purposes:

	City of Georgetown	PWS ID:	2460001
	PO Box 1430 Georgetown, Texas 78626	Contact Name: Phone Number:	Water Regulatory 512-930-3640
		BPAT Information	
Company Name: Fester Name: Address:	Safewater Backflow and Irrigation Brad Weyant 609 E 50TH AUSTIN, Texas 78751	Phone Number: Email Address: License Number: License Expiratior	5126059790 brad@safewateratx.com BP0016935 n: 12/3/2024
	Location Information		Contact Information
Property Type: Business Name: Property Address:	Residential 1808 Garrett Oaks Ln Georgetown, TX 78633	Company Name: Contact Name: Mailing Address: Phone Number: Email Address:	1808 Garrett Oaks Ln Georgetown, TX 78633
		Backflow Information	
The backflow prevention acceptable parameters.	assembly detailed below has been tes	ted and maintained as required by comm	ission regulations and is certified to be operating within
Backflow Method: Main Assembly Manufa Location: Hazard Type ****:	Double Check Valve acturer: Apollo N Right front yard 10 feet from meter Irrigation - Non Chemical	lodel: DC4A Size: 1	Serial Number: 98278C
		Backflow Test Information	
Fest Result: Reason for Test:	Passed New Installation		
-		s recommendations and/or local codes	s? Yes
s the assembly install Differential pressure	ed on a non-potable water supply (au MidWest 845-5 (potable)	uxiliary)? No Serial Number: 09231317	Date Tested for Accuracy: 3/14/2024
jauge used:			
	Doub	le Check Valve	
	Check Valve #1	Check Valve #2	
Initial Test Date: 10/15/2024 Time: 3:15 PM	Held at 1.9 PSID ClosedTight Leaked	Held at 2 PSID ClosedTight Leaked	
Repairs and Materials Used			
Repair Details			
Test After Repai	rs Held at 0 PSID	Held at 0 PSID	
		Remarks	

The above is certified to be true at the time of testing. * TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS [30 TAC 290.46(B)] ** USE ONLY MANUFACTURER'S REPLACEMENT PARTS *** 2nd Check: Numeric reading required for double check valve only. **** Indicates additional information not present on the standard TCEQ report