

4050 FM 1660 Hutto, Texas 78634 2983 512-759-1286 Fax 512-759-

## BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

PWS I.D: <b>2460022</b> MAILING ADDRESS_2003 Wynn Road Hutto, TX	78634	
CONTACT PERSONTaylor Morrison		
LOCATION OF SERVICE 2003 Wynn Road Hu		
NSPECTION DATE _12/18/2024_11:50AM		
The backflow prevention assembly detailed bel s certified to be operating within acceptable pa	w has been tested and maintained as required by TCEQ regulations a rameters.	no
	TYPE OF ASSEMBLY	
() Reduced Pressure ZONE	() Reduced Pressure Principle-Detector	
(X) Double Check Valve	() Double Check-Detector	
() Pressure Vacuum Breaker	() Spill-Resistant Pressure Vacuum Breaker	
Manufacturer: Apollo	_	
Model # DC4A	Serial # 85370C	
Location of device Right front yard 5	eet from meter	
s the assembly installed in accordance with ma	nufacturer recommendations and/or local codes? Yes	
Reduced Pr	ssure Principle Assembly Pressure Vacuum Br	ea

	Reduced I	Pressure Principle A	Pressure Vacuum Breaker		
	Double Check Valve Assembly		Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check		Opened at psid	Held at psid
Initial Test	Held at 2.1	Held at psid 2.3	Opened at psid	Did not Open	Leaked
	Closed Tight X Leaked □	Closed Tight X Leaked □	Did not open □		
Repairs and Materials Used					
Test After	Held at psid Closed Tight □	Held at psid Closed Tight □	Opened at psid	Opened at psid	Held At psid
Repair					

The above is certified to be true at the time of testing,

Test gauge used: Make / Model Mid West 845 SN: 09231317 Calibration Date:3/14/2024

Firm Name Safewater Backflow

Certified Tester: Brad Weyant

Firm Address PO Box 4002 Austin, TX 78765

Cert. Tester No: BP0016935

Firm Phone # 512-605-9790

- TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS \*\* USE ONLY MANUFACTURER'S REPLACEMENT PARTS