

4050 FM 1660 Hutto, Texas 78634 512-759-1286 Fax 512-759-2983

BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

PWS I.D: 2460022

MAILING ADDRESS_2006 Vanderscile Road Hutto, TX 78634_____ CONTACT PERSON __Taylor Morrison_____ LOCATION OF SERVICE 2006 Vanerscile Road Hutto, TX 78634_____ INSPECTION DATE _10/15/2024_4:40PM______

The backflow prevention assembly detailed below has been tested and maintained as required by TCEQ regulations and is certified to be operating within acceptable parameters.

|--|

() Reduced Pressure ZONE

(X) Double Check Valve

() Pressure Vacuum Breaker

- () Reduced Pressure Principle-Detector
- () Double Check-Detector
- () Spill-Resistant Pressure Vacuum Breaker

Manufacturer: Apollo_____

Model # DC4A_____ Serial # 94049C_____

Location of device Right front yard 5 feet from meter _____

Is the assembly installed in accordance with manufacturer recommendations and/or local codes? Yes_____

	Reduced Pressure Principle Assembly			Pressure Vacuum Breaker	
	Double Check Valve Assembly		Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check		Opened at psid	Held at psid
Initial Test	Held at 1.8 Psi	Held at 1.9 psid	Opened at psid	Did not Open 🛛	Leaked 🗆
	Closed Tight X Leaked □	Closed X Tight Leaked □	Did not open □		
Repairs and Materials Used					
Test After	Held at ps Closed Tight □	id Held at psid Closed Tight □	Opened at psid	Opened at psid	Held At psid
Repair					

The above is certified to be true at the time of testing,

Test gauge used: Make / Model Mid West 845

Firm Name Safewater Backflow

SN: 09231317

Certified Tester: Brad Weyant

Calibration Date:3/14/2024

Firm Address PO Box 4002 Austin, TX 78765

Cert. Tester No: BP0016935

Firm Phone # 512-605-9790

- TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS ** USE ONLY MANUFACTURER'S REPLACEMENT PARTS