City of Georgetown - Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly tested for recordkeeping *purposes:

	City of Georgetown PO Box 1430 Georgetown, Texas 78626	PWS ID: Contact Name: Phone Number:	2460001 Water Regulatory 512-930-3640
		BPAT Information	
Company Name: Tester Name: Address:	Safewater Backflow and Irrigation Brad Weyant 609 E 50TH AUSTIN, Texas 78751	Phone Number: Email Address: License Number License Expirati	
	Location Information		Contact Information
Property Type: Business Name: Property Address:	Residential 213 San Xavier St Georgetown, TX 78633	Company Name Contact Name: Mailing Address Phone Number: Email Address:	: 213 San Xavier St Georgetown, TX 78633
		Backflow Information	
The backflow prevention	assembly detailed below has been te	ested and maintained as required by com	mission regulations and is certified to be operating within
acceptable parameters. Backflow Method: Main Assembly Manuf Location: Hazard Type ****:	Double Check Valve acturer: Apollo Left front yard 5 feet from meter Irrigation - Non Chemical	Model: DC4A Size:	1 Serial Number: 85293C
		Backflow Test Information	
-	Passed New Installation ed in accordance with manufacture ed on a non-potable water supply (a	rs recommendations and/or local cod	es? Yes
Differential pressure gauge used:	MidWest 845-5 (potable)	Serial Number: 09231317	Date Tested for Accuracy: 3/14/2024
gauge usea.	Double Check Valve		
	Check Valve #1	Check Valve #2	
Initial Test Date: 11/26/2024 Time: 10:35 AM	Held at 2.2 PSID	Held at 1.9 PSID ✓ ClosedTight Leaked	
Repairs and Materials Use	d		
Repair Details	5		
Test After Repa	irs Held at 0 PSID	Held at 0 PSID	
		Remarks	

The above is certified to be true at the time of testing. * TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS [30 TAC 290.46(B)] ** USE ONLY MANUFACTURER'S REPLACEMENT PARTS *** 2nd Check: Numeric reading required for double check valve only. **** Indicates additional information not present on the standard TCEQ report