

4050 FM 1660 Hutto, Texas 78634 512-759-1286 Fax 512-759-2983

BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

PWS I.D: 2460022

MAILING ADDRESS__301 Doodle Ln. Hutto, TX 78634__ CONTACT PERSON _____Taylor Morrison____

LOCATION OF SERVICE 301 Doodle Ln. Hutto, TX 78634____

INSPECTION DATE _7/26/2023_12:00PM____

The backflow prevention assembly detailed below has been tested and maintained as required by TCEQ regulations and is certified to be operating within acceptable parameters.

() Reduced Pressure ZONE

(X) Double Check Valve

Pressure Vacuum Breaker ()

- () Reduced Pressure Principle-Detector
- () Double Check-Detector
- Spill-Resistant Pressure Vacuum Breaker ()

Manufacturer: Febco

_____ Serial # HG70023___ Model # 850

Location of device Left back yard 5 feet from meter _

Is the assembly installed in accordance with manufacturer recommendations and/or local codes? Yes_____

	Reduced Pressure Principle Assembly			Pressure Vacuum Breaker	
	Double Check Valve Assembly		Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check		Opened at psid	Held at psid
Initial Test	Held at 2.3 Psi	Held at 2.2 psid	Opened at psid	Did not Open 🛛	Leaked 🗆
	Closed Tight X Leaked □	Closed Tight X Leaked □	Did not open 🛛		
Repairs and Materials Used					
Test After	Held at psid Closed Tight □	Held at psid Closed Tight □	Opened at psid	Opened at psid	Held At psid
Repair					

The above is certified to be true at the time of testing,

Test gauge used: Make / Model Mid West 845 SN: 10150482 Calibration Date:10/5/2022

Firm Name Safewater Backflow

Certified Tester: Brad Weyant

Firm Address PO Box 4002 Austin, TX 78765

Cert. Tester No: BP0016935

Firm Phone # 512-605-9790

Pressure 60

- TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS ** USE ONLY MANUFACTURER'S REPLACEMENT PARTS